

AD-A105 106

ANDERSON ENGINEERING INC SPRINGFIELD MO

F/G 13/13

NATIONAL DAM SAFETY PROGRAM. DAM C-23 (MO 10283, MISSOURI - KAN--ETC(U)


DEC 78 J M HEALY, S L BRADY

DACW43-78-C-0166

NL

UNCLASSIFIED

1-14
40-4
1-1-77



AD A105106

LEVEL II

①

MISSOURI - KANSAS CITY BASIN

B-3

DAM C-23

LAFAYETTE COUNTY, MISSOURI

MO 10283

DTIC
ELECTE
OCT 0 5 1981
S D E

PHASE I INSPECTION REPORT
6 NATIONAL DAM SAFETY PROGRAM.

Dam C-23 (MO 10283, Missouri - Kansas
City Basin, Lafayette County, Missouri.
Phase I Inspection Report.



9 Final rept.,

15 DACW43-78-C-0166

10 John M. /Healy Steven L. /Brady

PREPARED BY: U. S. ARMY ENGINEER DISTRICT, ST. LOUIS

FOR: STATE OF MISSOURI

This document has been approved
for public release and sale; its
distribution is unlimited.

⑫ 74

⑪ DEC 1978

81 10 2 224

FILE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered).

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. AD-A105 106	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program Dam C-23 (MO 10283) Lafayette County, Missouri		5. TYPE OF REPORT & PERIOD COVERED Final Report
7. AUTHOR(s) Anderson Engineering, Inc.		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		8. CONTRACT OR GRANT NUMBER(s) DACW43-78-C-0166
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE December 1978
		13. NUMBER OF PAGES Approximately 55
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety, Lake, Dam Inspection, Private Dams		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property.		


DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

INSTRUCTIONS FOR PREPARATION OF REPORT DOCUMENTATION PAGE

RESPONSIBILITY. The controlling DoD office will be responsible for completion of the Report Documentation Page, DD Form 1473, in all technical reports prepared by or for DoD organizations.

CLASSIFICATION. Since this Report Documentation Page, DD Form 1473, is used in preparing announcements, bibliographies, and data banks, it should be unclassified if possible. If a classification is required, identify the classified items on the page by the appropriate symbol.

COMPLETION GUIDE

General. Make Blocks 1, 4, 5, 6, 7, 11, 13, 15, and 16 agree with the corresponding information on the report cover. Leave Blocks 2 and 3 blank.

Block 1. Report Number. Enter the unique alphanumeric report number shown on the cover.

Block 2. Government Accession No. Leave Blank. This space is for use by the Defense Documentation Center.

Block 3. Recipient's Catalog Number. Leave blank. This space is for the use of the report recipient to assist in future retrieval of the document.

Block 4. Title and Subtitle. Enter the title in all capital letters exactly as it appears on the publication. Titles should be unclassified whenever possible. Write out the English equivalent for Greek letters and mathematical symbols in the title (see "Abstracting Scientific and Technical Reports of Defense-sponsored RDT/E," AD-667 000). If the report has a subtitle, this subtitle should follow the main title, be separated by a comma or semicolon if appropriate, and be initially capitalized. If a publication has a title in a foreign language, translate the title into English and follow the English translation with the title in the original language. Make every effort to simplify the title before publication.

Block 5. Type of Report and Period Covered. Indicate here whether report is interim, final, etc., and, if applicable, inclusive dates of period covered, such as the life of a contract covered in a final contractor report.

Block 6. Performing Organization Report Number. Only numbers other than the official report number shown in Block 1, such as series numbers for in-house reports or a contractor/grantee number assigned by him, will be placed in this space. If no such numbers are used, leave this space blank.

Block 7. Author(s). Include corresponding information from the report cover. Give the name(s) of the author(s) in conventional order (for example, John R. Doe or, if author prefers, J. Robert Doe). In addition, list the affiliation of an author if it differs from that of the performing organization.

Block 8. Contract or Grant Number(s). For a contractor or grantee report, enter the complete contract or grant number(s) under which the work reported was accomplished. Leave blank in in-house reports.

Block 9. Performing Organization Name and Address. For in-house reports enter the name and address, including office symbol, of the performing activity. For contractor or grantee reports enter the name and address of the contractor or grantee who prepared the report and identify the appropriate corporate division, school, laboratory, etc., of the author. List city, state, and ZIP Code.

Block 10. Program Element, Project, Task Area, and Work Unit Numbers. Enter here the number code from the applicable Department of Defense form, such as the DD Form 1498, "Research and Technology Work Unit Summary" or the DD Form 1634, "Research and Development Planning Summary," which identifies the program element, project, task area, and work unit or equivalent under which the work was authorized.

Block 11. Controlling Office Name and Address. Enter the full, official name and address, including office symbol, of the controlling office. (Equates to funding/sponsoring agency. For definition see DoD Directive 5200.20, "Distribution Statements on Technical Documents.")

Block 12. Report Date. Enter here the day, month, and year or month and year as shown on the cover.

Block 13. Number of Pages. Enter the total number of pages.

Block 14. Monitoring Agency Name and Address (if different from Controlling Office). For use when the controlling or funding office does not directly administer a project, contract, or grant, but delegates the administrative responsibility to another organization.

Blocks 15 & 15a. Security Classification of the Report: Declassification/Downgrading Schedule of the Report. Enter in 15 the highest classification of the report. If appropriate, enter in 15a the declassification/downgrading schedule of the report, using the abbreviations for declassification/downgrading schedules listed in paragraph 4-207 of DoD 5200.1-R.

Block 16. Distribution Statement of the Report. Insert here the applicable distribution statement of the report from DoD Directive 5200.20, "Distribution Statements on Technical Documents."

Block 17. Distribution Statement (of the abstract entered in Block 20, if different from the distribution statement of the report). Insert here the applicable distribution statement of the abstract from DoD Directive 5200.20, "Distribution Statements on Technical Documents."

Block 18. Supplementary Notes. Enter information not included elsewhere but useful, such as: Prepared in cooperation with . . . Translation of (or by) . . . Presented at conference of . . . To be published in . . .

Block 19. Key Words. Select terms or short phrases that identify the principal subjects covered in the report, and are sufficiently specific and precise to be used as index entries for cataloging, conforming to standard terminology. The DoD "Thesaurus of Engineering and Scientific Terms" (TEST), AD-672 000, can be helpful.

Block 20. Abstract. The abstract should be a brief (not to exceed 200 words) factual summary of the most significant information contained in the report. If possible, the abstract of a classified report should be unclassified and the abstract to an unclassified report should consist of publicly-releasable information. If the report contains a significant bibliography or literature survey, mention it here. For information on preparing abstracts see "Abstracting Scientific and Technical Reports of Defense-Sponsored RDT&E," AD-667 000.



DEPARTMENT OF THE ARMY
ST. LOUIS DISTRICT, CORPS OF ENGINEERS
210 NORTH 12TH STREET
ST. LOUIS, MISSOURI 63101

IN REPLY REFER TO

SUBJECT: Dam C-23 Phase I Inspection Report

This report presents the results of field inspection and evaluation of Dam C-23. It was prepared under the National Program of Inspection of Non-Federal Dams.

SIGNED

26

1979

SUBMITTED BY:

Chief, Engineering Division

Date

SIGNED

26

1979

APPROVED BY:

Colonel, CE, District Engineer

Date

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	

DAM C-23
LAFAYETTE COUNTY, MISSOURI
MISSOURI INVENTORY NO. 10283

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Prepared By
Anderson Engineering, Inc., Springfield, Missouri
Hanson Engineers, Inc., Springfield, Illinois

For
The Governor of Missouri

December, 1978

PHASE I REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Dam C-23
State Located: Missouri
County Located: Lafayette County
Stream: Unnamed Tributary to Missouri River
Date of Inspection: 2 August 1978


Dam C-23 was inspected by an interdisciplinary team of engineers from Anderson Engineering, Inc. of Springfield, Missouri and Hanson Engineers, Inc. of Springfield, Illinois. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.


The guidelines used in the assessment were furnished by the Department of the Army, Office of the Chief of Engineers and they have been developed with the help of several Federal and State agencies, professional engineering organizations, and private engineers. Based on these guidelines, this dam has been classified by the St. Louis District Corps of Engineers as an intermediate size dam with a high downstream hazard potential. Their estimate of the damage zone extends 4 miles downstream of the dam. Lafayette County Dam C-22 is about 1/2 mile downstream of Dam C-23. If Dam C-23 should fail, then Dam C-22 also would likely fail. Within the damage zone are three houses, (two of which have associated farm buildings), one unimproved road crossing, one railroad bridge and one U.S. Highway Bridge.

Our inspection and evaluation indicates that the combined spillways do not meet the criteria set forth in the guidelines for a dam having the above size and hazard potential. The combined spillways will pass 54 percent of the Probable Maximum Flood without overtopping. The Probable Maximum Flood (PMF) is defined as the flood discharge that may be expected from the most severe combination of critical meteorological and hydrologic conditions that are reasonably possible in the region. The guidelines require that a dam

of intermediate size with a high downstream hazard potential pass 100 percent of the PMF. The combined spillways will pass the 100-year flood, without overtopping.

The embankment and appurtenances are generally in good condition. Minor deficiencies, including erosion, tree growth and animal burrows, were noted and should be corrected by the owner. It was noted that the lake has never filled and suggestions were made for further investigation of under-seepage potential and possible associated dangers in this regard. Another deficiency was the lack of seepage analysis data. A detailed report is attached to be submitted to the owners and to the Governor of Missouri.


John M. Healy, P.E.
Hanson Engineers, Inc.


Steven L. Brady, P.E.
Anderson Engineering, Inc.

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
DAM C-23 - ID NO. 10283

TABLE OF CONTENTS

<u>Paragraph No.</u>	<u>Title</u>	<u>Page No.</u>
SECTION 1 - PROJECT INFORMATION		
1.1	General	1
1.2	Description of Project	1
1.3	Pertinent Data	3
SECTION 2 - ENGINEERING DATA		
2.1	General	6
2.2	Design	6
2.3	Construction	8
2.4	Operation and Maintenance	8
2.5	Evaluation	9
SECTION 3 - VISUAL INSPECTION		
3.1	General	10
3.2	Dam	10
3.3	Reservoir and Watershed	12
3.4	Evaluation	12
SECTION 4 - OPERATIONAL PROCEDURES		
4.1	Procedures	13
4.2	Maintenance of Dam	13
4.3	Maintenance of Operating Facilities	13
4.4	Description of Any Warning System in Effect	13
4.5	Evaluation	13
SECTION 5 - HYDRAULIC/HYDROLOGIC		
5.1	Evaluation of Features	14
SECTION 6 - STRUCTURAL STABILITY		
6.1	Evaluation of Structural Stability	16
SECTION 7 - ASSESSMENT/REMEDIAL MEASURES		
7.1	Dam Assessment	17
7.2	Further Investigations	18
7.3	Remedial Measures	19

APPENDICES

Sheet

APPENDIX A

Vicinity Map	1
Site Plan	2
Plan and Section of Dam	3
Plan and Profile of Primary Spillway	4
Profile of Foundation Drainage System	5

APPENDIX B

Boring Location Plan	1
Profile of Subsurface Materials	2
Geologic Report	3 thru 5
Soil Testing Report and Recommendations	6 thru 9
Hydrologic and Hydraulic Design	10 thru 12

APPENDIX C

Overtopping Analysis - PMF	1 thru 7
----------------------------	----------

APPENDIX D

Photographs of Dam, Lake and Watershed	1 thru 5
--	----------



Aerial View of Lake and Dam

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL:

A. Authority:

The National Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of safety inspection of dams throughout the United States. Pursuant to the above, the St. Louis District, Corps of Engineers, District Engineer directed that a safety inspection of Dam C-23 in Lafayette County, Missouri be made.

B. Purpose of Inspection:

The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and a visual inspection in order to determine if the dam poses hazards to human life or property.

C. Evaluation Criteria:

Criteria used to evaluate the dam were furnished by the Department of the Army, Office of the Chief of Engineers, "Recommended Guidelines For Safety Inspection of Dams." These guidelines were developed with the help of several federal agencies and many state agencies, professional engineering organizations, and private engineers.

1.2 DESCRIPTION OF PROJECT:

A. Description of Dam and Appurtenances:

Dam C-23 is an earth fill structure approximately 50 ft high and 500 ft long at the crest. The appurtenant works consist of a concrete drop inlet and reinforced concrete pipe primary spillway, which is located near the center of the dam, and a grass covered emergency spillway, which is located at the north abutment. Sheet 3 of Appendix A shows a plan of the embankment and spillways and a typical section of the embankment.

B. Location:

The dam is located in the northwest part of Lafayette County, Missouri on a small tributary of the Missouri River. The dam and lake are within the Bates City, Missouri quadrangle sheet, 1 1/2 miles west and 1/2 mile south

of Wellington (SW 1/4 Section 20, Twp. 15 N, R 28 W-latitude 39° 7.4'; longitude 94° 1.4'). Sheet 1 of Appendix A shows the general vicinity and location of the dam. Sheet 2 shows a plan of the immediate area of the dam and lake.

C. Size Classification:

With an embankment height of 50 ft and a maximum storage capacity of approximately 232 acre-ft, the dam is in the intermediate size category.

D. Hazard Classification:

The St. Louis District, Corps of Engineers has classified this dam as a high hazard dam. Their estimate of the damage zone extends 4 miles downstream of the dam. Lafayette County Dam C-22 is about 1/2 mile downstream of Dam C-23. If Dam C-23 should fail, then Dam C-22 would likely fail. Also within the damage zone are three houses (two of which have associated farm buildings), one unimproved road crossing, one railroad bridge and one U.S. Highway Bridge.

E. Ownership:

The dam was designed by the Soil Conservation Service (SCS) but the property upon which the dam and lake are located is retained by the property owner or owners. These owners granted an easement to the Wellington-Napolean Watershed Subdistrict to construct, operate, and maintain this structure. The subdistrict is the owner and is responsible for the structure. The address of the subdistrict is 120 West 19th Street, Higginsville, Missouri 64057. The As-Built plans indicate the primary owners to be Omer and Erna Borgman. The tenant who provided access to the dam is Mr. Bohall.

F. Purpose of Dam:

The purpose of the PL-566 watershed program is to provide watershed protection and flood prevention. The purpose of these structures is for grade stabilization with flood water retarding features. These lakes may be stocked with fish but not by the Soil Conservation Service. They may be stocked with fish from the Federal and State Fisheries in cooperation with individual landowners.

G. Design and Construction History:

The dam was designed by the Soil Conservation Service and constructed under their inspection supervision (inspection handled by the Higginsville District Office). The dam was completed in 1970. As-Built plans are available and have been used to prepare this report. No significant problems in regards to seepage through or stability of the embankment are reported to have occurred since the dam was built. According to SCS district personnel, no modifications have been made to the dam.

H. Normal Operating Procedure:

Normal flows will be passed by an uncontrolled drop inlet spillway, whereas a grassed emergency spillway would come into operation for major floods. Local SCS personnel have indicated that the lake has never filled so that neither the primary spillway nor the emergency spillway have been in service (see Section 7.2.A of this report).

1.3 PERTINENT DATA:

Pertinent data about the dam, appurtenant works, and reservoir are presented in the following paragraphs. Sheet 3 of Appendix A is a plan of the embankment and spillways with a typical cross section of the dam. Sheet 4 presents a plan and profile of the primary spillway. Sheet 5 presents a profile and cross section of the foundation drainage system.

A. Drainage Area:

The drainage area for this dam, as obtained from the Bates City, Missouri and Camden, Missouri 7.5 minutes quad sheets, is equal to approximately 146 acres.

B. Elevations (Feet Above M.S.L.):

- (1) Top of dam (measured): north end 783.2; center 783.8; south end 782.8.
Top of Dam (As-Built Plans): north end 782.7; center 784.5; south end 782.5.
- (2) Principal Spillway Crest: As-Built Plans 777.0; measured 776.3.
- (3) Emergency Spillway Crest: As-Built Plans 779.5; measured 779.6.

- (4) Primary Spillway Outlet Pipe Invert: As-Built Plans 740.0; measured 739.9.
- (5) Maximum Design Pool (As Built Plans): 781.7.
- (6) Pool on Date of Inspection: measured 761.7.
- (7) Apparent High Water Mark on Date of Inspection: measured 766.0.
- (8) Streambed at Downstream Toe of Dam: As-Built Plans 736.5; measured 736.6.
- (9) Maximum Tailwater: Unknown.

C. Discharge at Dam Site:

- (1) All discharge at the dam site is through uncontrolled spillways.
- (2) Estimated Discharge Capacity at Top of Dam (El. 782.8): 327 cfs.

D. Reservoir Surface Areas:

- (1) At Principal Spillway Crest: As Built Plans 11.8 acres.
- (2) At Top of Dam (El. 782.8): 17 acres. Extrapolated from table on As-Built Plans (see Sheet 10 of Appendix B).

E. Storage Capacities:

- (1) At Principal Spillway Crest: 148 acre-ft.
- (2) At Top of Dam (El. 782.8): 232 acre-ft. (See Sheet 7 of Appendix C.)

F. Reservoir Lengths:

- (1) At Principal Spillway Crest (Estimated from As-Built Plans): 1750 ft.
- (2) At Top of Dam (Estimated from As-Built Plans): 1900 ft.

G. Dam:

- (1) Type: rolled earth.
- (2) Length at Crest: 500 ft.
- (3) Height: 50 ft.
- (4) Top Width: 14 ft.
- (5) Side Slopes: 2.5 H: 1 V.
- (6) Zoning: homogeneous silts and clays.
- (7) Cutoff: shallow core trench.

H. Principal Spillway:

- (1) Location: center of dam--Station 3+65.
- (2) Type: 2 ft by 6 ft drop inlet concrete structure (crest El. 776.3; 12 ft in length) with a 24 in. diameter reinforced concrete outlet pipe through the dam. The outlet pipe is 184 ft long and is supported on a type A3 cradle, with 4 concrete antiseep collars. The pipe inlet invert is at El. 751.0 and the outlet invert is at El. 740.0 (see Sheet 4 of Appendix A). No stilling basin is provided at the end of the primary spillway outlet pipe; a plunge pool is expected to be created.

I. Emergency Spillway:

- (1) Location: north abutment.
- (2) Type: grass covered earth with 20 ft crest length and 3 H: 1 V side slopes.

SECTION 2 - ENGINEERING DATA

2.1 GENERAL:

Available design computations and reports for Dam C-23 include a geology and soils report which contains soils testing information for the foundation and borrow materials (includes soil classifications, grain size analyses, shear strength tests, consolidation tests and permeability tests). Based on this information, design recommendations were made regarding site preparation, foundation drainage and embankment configurations. The As-Built plans contain a summary of the hydrologic and hydraulic design data used for the primary and emergency spillways. No documentation of construction inspection records have been obtained. There are no documented maintenance and operation data to our knowledge.

2.2 DESIGN:

A. Surveys:

The As-Built drawings show the topography of the immediate dam site area (Sheets 2 and 3 of Appendix A). A bench mark in the form of a brass cap in a concrete monument is located in a fence corner on the emergency spillway end of the dam, approximately 50 ft north of the west gate (BM C-23 elevation = 764.75).

B. Geology and Subsurface Materials:

Physiographically, the site is located in the Missouri River loess hills area, which is characterized by gently rolling topography. The subsurface materials in upland areas generally consist of in excess of 20 ft of loess underlain by a Kansan Age glacial till material. Geological maps of the area indicate that the bedrock is the Marmaton group of the upper Desmoinesian series of the Pennsylvanian system. The Marmaton group consists of a succession of shale, limestone, clay and coal beds.

A publication entitled "Evaluation of Missouri's Coal Resources" by the Missouri Geological Survey indicates that the "Lexington Coal Bed" was mined extensively in this area. The maps associated with this publication indicate that the dam site lies near the southern boundary of the undermining activity and that the coal seam mined was approximately 20 in. thick in the area. The U.S.G.S. quad sheet for the area (Camden, Missouri, 1950) indicates an inactive mine shaft

approximately 1 1/2 miles northeast of the dam (see Sheet 1 of Appendix C). The Coal Resources publication previously mentioned indicates that the depth to the coal seam at that location is approximately 32 ft and that the thickness of the seam is 18 in. If the coal seam is horizontal, then it would be at a depth of approximately 70 ft below the stream bed at the center of the dam (coal seam at elevation 660 to 665).

A boring plan and description of the soils encountered in the borings (Sheets 15 and 16 of the As-Built plans) are presented as Sheets 1 and 2 of Appendix B. Sheets 3, 4 and 5 of Appendix B present a description of the surface geology and physiography, and interpretations and conclusions regarding the soils encountered in the boring program (from geology and soils report by SCS). The soils encountered in the borings are generally low plasticity clays and silts to a depth of approximately 30 ft below the ground surface. Dry density determinations on "core" samples were between 1.2 g/cc (74.9 pcf) and 1.5 per g/cc (93.6 pcf) and estimated "blow counts" were between 5 and 10. A sand material was encountered at a depth of approximately 30 ft in Borings 3, 301 and 302 (top of sand layer at elevation 710 to 730). The maximum penetration of the borings was to approximate elevation 700. "Refusal" was encountered in borings for Dam A-21 (adjacent watershed) at elevation 675 to 680 (possible elevation of bedrock in the area).

C. Foundation and Embankment Design:

Reference should be made to Sheets 6 through 9 of Appendix B which contain a summary of the soil test data and recommendations for the foundation and embankment design (from geology and soils report by SCS). Because of the existence of sand layers and the possibility of boils occurring in the plunge pool area, a foundation drainage system was developed (includes a drainage trench and two vertical drains penetrating to elevation 708). The foundation drainage system is shown on Sheets 4 and 5 of Appendix A (from As-Built Plans). A shallow core trench apparently was constructed at the base of the dam along its entire length.

Borrow material for the dam was obtained from the reservoir area upstream of the embankment. Stability analyses based on the use of this material were performed by SCS. It was recommended that the embankment materials be

compacted to 95 percent of the maximum dry density as obtained by the Standard Proctor Compaction Test and at a moisture content wet of optimum. There is apparently no particular zoning of the embankment, and no internal drainage features (except for the previously described foundation drainage system) are known to exist. No construction inspection test results have been obtained.

D. Hydrology and Hydraulics:

Design data, storage curves and routing curves for the "emergency spillway" and "freeboard" hydrographs are presented on Sheets 10 through 12 of Appendix B (from As-Built plans by SCS). Based on this data, a field check of spillway dimensions and embankment elevations, and a check of the drainage area on U.S.G.S. quad sheets, a hydrologic analysis using U.S. Army Corps of Engineers guidelines was performed and appears in Appendix C, Sheets 1 to 7. It was concluded that the primary and emergency spillways combined will pass 54 percent of the Probable Maximum Flood.

E. Structure:

Structural design computations for appurtenant structures were not obtained. Details of all concrete structural elements (riser structure, etc.) are shown on the As-Built plans.

2.3 CONSTRUCTION:

No construction inspection data has been obtained. Construction supervision was accomplished by the Soil Conservation Service district local office in Higginsville, Missouri.

2.4 OPERATION AND MAINTENANCE:

On this structure, there is an operation and maintenance agreement between the Soil Conservation Service and the Wellington-Napolean Watershed Subdistrict. The operation and maintenance agreement spells out the operation and maintenance requirements and the inspection procedures. Regional SCS office personnel indicated that a yearly questionnaire is sent to land owners inquiring as to maintenance problems. It was reported that inspection stops are made on an irregular basis by SCS district personnel (Higginsville office).

2.5 EVALUATION:

The available engineering data did include slope stability analyses but no seepage analyses, although seepage analyses apparently have been performed (see discussion of uplift on Sheet 7 of Appendix B). The owner should locate these analyses or have an engineer experienced in the design of dams perform detailed seepage analyses.

The engineering data available were inadequate to make a detailed assessment of the design and particularly the construction of the dam. No valid engineering data on the construction of the dam were found.

SECTION 3 - VISUAL INSPECTION

3.1 GENERAL:

The field inspection was made on 2 August 1978. The inspection team consisted of personnel from Anderson Engineers, Inc. of Springfield, Missouri and Hanson Engineers, Inc. of Springfield, Illinois. The team members were:

Mike Gray - Anderson Engineers
(Instrument Man)

Steve Brady - Anderson Engineers
(Civil Engineer)

Jack Healy - Hanson Engineers
(Geotechnical and Structural Engineer)

Gene Wertepny - Hanson Engineers
(Hydraulics Engineer)

Dave Daniels - Hanson Engineers
(Geotechnical and Hydraulics Engineer)

3.2 DAM:

The dam is an earth fill embankment constructed from borrow obtained from the emergency spillway area and the reservoir area below normal pool. Based on the soil borings, the fill material would be expected to consist of low plasticity clays and silts.

The embankment is grass covered and appears to good condition. A few one to two year old trees (willows and cottonwoods) were growing on the front face of the dam between elevations 762 and 766. No sloughing of the embankment or seepage through or under the embankment was evident. The foundation drain outlet was dry. There was some slight erosion at the downstream embankment-abutment contacts (more pronounced on the south abutment). Also, there was some slight erosion on the upstream face of the dam below the primary spillway crest. An animal burrow (shallow hole \pm 3 ft deep) was noted on the outside edge of the downstream berm 60 ft from the south abutment.

The horizontal alignment appeared as constructed. No surface cracking or unusual movement was obvious. It should be noted, however, that elevations of the primary spillway crest and the center of the dam which were obtained in the field were approximately 0.5 ft lower than as indicated on the As-Built Plans (see Section 1.3.B of this report). All other elevations obtained in the field agreed fairly well with those indicated on the As-Built Plans. The discrepancy at the center of the dam might be explained by the possibility of some post construction settlement of the center portion of the dam.

No instrumentation (monuments, piezometers, etc.) were observed.

A. Primary Spillway and Outlet:

The riser structure was in good condition--no cracking or spalling of concrete was noted. The intake structure was surrounded by heavy grass.

The outlet pipe of the primary spillway was also in good condition. There was a very small flow dripping from the outlet pipe which could indicate some possible joint leakage. As mentioned previously the pool level was well below the crest of the primary spillway. Joint leakage could be associated with the possible embankment settlement discussed above. There is no energy dissipator at the end of the outlet pipe; a plunge pool is expected to be created for this purpose.

The channel downstream of the outlet pipe was grass and weed covered for the first 50 ft. Beyond 50 ft, the channel was lined with trees and brush. No plunge pool has been formed indicating that the primary spillway has probably never been used. The downstream channel empties into a lower lake approximately 500 ft downstream of the outlet pipe. There is a small check dam in the outlet channel at the upstream edge of the lower lake. Water in the outlet channel was not flowing and was stagnant. No significant erosion or sloughing of outlet channel slopes was noted.

Along the last portion of the primary spillway outlet pipe, there is a 6 in. diameter asbestos cement (pressure) pipe, class 100, which is the outlet of the foundation drainage system. The pipe has a length of 90 ft and a slope of 0.010. It is shown in the photographs on Sheet 1, 2 and 4 of Appendix D and in Sheets 4 and 5 of Appendix A.

B. Emergency Spillway:

The emergency spillway is in good condition. It measures 20 ft in width with 3 H: 1 V side slopes. The base and side slopes of the emergency spillway are grass covered. No erosion was noted and it appears that the emergency spillway has never been used.

3.3 RESERVOIR AND WATERSHED:

The immediate periphery of the lake was grass covered with moderate slopes. No sloughing or serious erosion of reservoir banks were noted.

The lake has apparently never filled. The apparent high water mark is at elevation 766, which is 11 ft below the primary spillway crest (primary spillway crest at elevation 777.0).

3.4 EVALUATION:

Small tree growths noted on the front face of the dam should be removed and all future growth should be removed on a yearly basis. Grass should be cut around the primary spillway crest. Excessive growths in this area could cause entrance restrictions. Visually observed erosional areas and animal burrows are deficiencies which, if left uncontrolled or uncorrected, could lead to serious problems in the future. These deficiencies should be able to be corrected by normally scheduled routine maintenance.

Photographs of the dam, appurtenant structures, and the reservoir and watershed are presented in Appendix D.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES:

There are no controlled outlet works for this dam; therefore, no regulating procedures exist. The pool is controlled by rainfall, runoff, evaporation and the capacities of the uncontrolled spillways.

4.2 MAINTENANCE OF DAM:

Maintenance in terms of tree and brush removal and mowing of the grass is apparently the responsibility of the land owner. A yearly questionnaire is sent to land owners inquiring as to maintenance problems. Inspection stops are reported to be made on an irregular basis by SCS regional personnel.

4.3 MAINTENANCE OF OPERATING FACILITIES:

No operating facilities exist at this dam.

4.4 DESCRIPTION OF ANY WARNING SYSTEM AND AFFECT:

The inspection team is unaware of any existing warning system for this dam.

4.5 EVALUATION:

Tree and brush growth should be removed from the dam on a yearly basis. Animal burrows or other holes in the dam should be filled. Erosional areas at abutment-dam contacts should be repaired. The use of riprap to prevent future erosion in these areas is a possibility.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES:

A. Design and Experience Data:

Design data used by the Soil Conservation Service to design this dam are shown on the As-Built plans and presented as Sheets 10 through 12 of Appendix B of this report. Based on this information, a field check of spillway dimensions and embankment elevations, and a check of the pool and drainage areas from U.S.G.S. quad sheets (Bates City Missouri and Camden, Missouri quad sheets), a hydrologic analysis using U.S. Army Corps of Engineers guidelines was performed and appears in Appendix C, Sheets 1 to 7.

B. Visual Observations:

The riser structure and outlet pipe for the primary spillway appear in good condition. A small flow from the outlet pipe (lake level below spillway crest) indicates the possibility of some pipe joint leakage. The earth and grass covered emergency spillway is in good condition. Neither the primary nor the emergency spillway have apparently ever been used.

No facilities are available to draw down the pool. The primary spillway is located near the center of the dam and the emergency spillway is located on the north abutment. Spillway releases would not be expected to endanger the integrity of the dam.

C. Overtopping Potential:

Based on the hydrologic and hydraulic analysis as presented in Appendix C, the combined primary and emergency spillways will not pass the Probable Maximum Flood without overtopping. The Probable Maximum Flood (PMF) is defined as the flood discharge that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region. The recommended guidelines from the Department of the Army, Office of the Chief of Engineers, require that this structure (intermediate size with high downstream hazard potential) pass 100 percent of the PMF, without overtopping. The routing of the PMF through the spillways and Dam, indicated that the Dam will be overtopped by 1.17 ft at reservoir elevation 783.97. The duration of the overtopping will be 3.17 hrs. and the maximum outflow 2522 cfs. Fifty percent of the PMF

was also routed through the spillways, resulting in a maximum reservoir elevation of 782.68, 0.12 ft below the lowest elevation of the dam (782.8). The peak outflow was 319 cfs. The portion of the PMF that will just reach the top of the dam is about 54 percent. The spillway system will be able to pass the 100 year frequency flood without overtopping.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY:

A. Visual Observations:

No serious deficiencies which would affect the structural stability of this dam were noted during the field inspection. However, if left unchecked, tree growth, animal burrows and the erosion at abutment-dam contact areas could cause stability problems in the future. The possibility of some joint leakage in the primary spillway outlet pipe should be periodically checked and investigated if it increases.

B. Design and Construction Data:

Stability analyses were performed by the Soil Conservation Service and recommendations were made regarding side slopes, berm widths and compaction densities (see Sheets 6 through 9 of Appendix B). Our site inspection indicated that the side slopes and berm widths were as recommended. If the embankment was placed in relatively thin lifts at the recommended density of 95 percent of the Standard Proctor maximum dry density (no laboratory testing records available to verify this), then the embankment should remain stable. A seepage analysis comparable to the requirements of the guidelines was not available which is considered a deficiency and should be corrected.

C. Operating Records:

No appurtenant structures requiring operation exist at this dam.

D. Post-Construction Changes:

To our knowledge, no post-construction changes have been made.

E. Seismic Stability:

Considering the seismic zone (I) in which this dam is located, an earthquake of this magnitude is not expected to cause a structural failure to this dam.

SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

7.1 DAM ASSESSMENT:

A. General:

This Phase I inspection and evaluation should not be considered as being comprehensive since the scope of work contracted for is far less detailed than would be required for an in-depth evaluation of dams. Latent deficiencies, which might be detected by a totally comprehensive investigation, could exist.

B. Safety:

The embankment itself is generally in good condition. A seepage analysis comparable to the requirements of the guidelines was not available, which is considered a deficiency and should be corrected. The possibility of some joint leakage in the primary spillway outlet pipe should be investigated. Also, the minor items which have been noted previously such as tree growth, animal burrows and abutment-dam contact erosion areas can and should be corrected and controlled.

The dam will be overtopped by flows in excess of 54 percent of the Probable Maximum Flood. Overtopping of an earthen embankment could cause serious erosion and could possibly lead to failure of the structure.

C. Adequacy of Information:

The conclusions in this report were based on review of the As-Built plans, the geologic and soil mechanics report prepared by the Soil Conservation Service, the performance history as related by others, and visual observation of external conditions. The inspection team considers that these data are sufficient to support the conclusions herein.

D. Urgency:

The remedial measures recommended in paragraph 7.3 should be accomplished in the near future. If the minor deficiencies listed in paragraph B are not corrected and if good maintenance is not provided, the embankment condition will continue to deteriorate and it could become serious in the future.

E. Necessity for Phase II:

Based on the results of the Phase I inspection, no Phase II inspection is recommended.

F. Seismic Stability:

This dam is located in Seismic Zone 1. An earthquake of this magnitude is not expected to be hazardous to this dam.

7.2 FURTHER INVESTIGATIONS:

A. Reservoir:

As mentioned previously this lake has never filled. Conversations with the state geologist have indicated that at least one lake in the area has apparently been leaking through abandoned mine shafts. However, the land owner and a former mine operator in the area have indicated that they do not believe that lake C-23 is undermined. Thus, the fact that the lake has never filled is probably not due to leakage through abandoned mine shafts.

It is also possible that leakage could be occurring through the underlying sand lenses encountered in the borings. No seepage was noted in the area immediately downstream of the dam. However, deeper substratum leakage into adjacent watersheds or lakes is a possibility, although somewhat remote due to the long distances involved. It should be noted in this regard that the pool elevation of lake C-23 was essentially the same as the pool elevation of lake A-21 (in an adjacent watershed--was inspected the following day). It is suggested that the possibility of leakage through sand layers be investigated further.

B. Outlet Pipe:


A very small amount of water was exiting from the outlet pipe on the day of the inspection. The source of the water could not be explained since the spillway was not flowing. The possibility of some joint leakage is suggested. Although apparently not serious at this time, this condition should be evaluated by local maintenance personnel.


7.3 REMEDIAL MEASURES:

The following remedial measures and maintenance procedures are recommended and should be performed under the guidance of a professional engineer experienced in the design and construction of dams.

- (1) Spillway size and/or height of dam should be increased to pass the PMF. In either case, the spillway should be protected to prevent erosion.
- (2) A seepage analysis comparable to the requirements of the guidelines was not available, which is considered a deficiency and should be corrected.
- (3) Remove existing tree growth on the upstream face of the dam and remove all future tree and brush growth on a yearly basis. Cut the high grass around the primary spillway to prevent restrictions.
- (4) Fill the animal burrow. Correct the minor erosion activity at the embankment-abutment contact on the downstream side of the dam and place riprap in these areas to minimize erosion in the future.
- (5) Check the downstream slope periodically for seepage and stability problems. If wet areas or seepage flows are observed, or if sloughing is noted, then the dam should be inspected and the situation evaluated by an engineer experienced in design and construction of dams.
- (6) A detailed inspection of the dam should be made at least every 5 years by an engineer experienced in the design and construction of dams. More frequent inspections may be required if slides, seeps, or other items of distress are observed.

APPENDIX A





INDEX OF DRAWINGS	
Cover Sheet	1
General Plan of Reservoir	2
Plan of Embankment & Spillways	3
General Layout	4
Foundation Drainage System	5
Pipe Requirements	6
Outlet Details	7
Artisano Details	8
Inlet Details	9
Trash Rack Details	10
Fence Details	11
Standard Details	12
Plan - Geologic Investigation	13
Profile - Geologic Investigation	14
Cross Sections - Geologic Investigation	15

U S DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

**DETAIL PLANS FOR
WELLINGTON-NAPOLEON
WATERSHED PROTECTION AND
FLOOD PREVENTION PROJECT**


LAFAYETTE COUNTY, MISSOURI
IN COOPERATION WITH
SOIL AND WATER CONSERVATION DISTRICT
OF LAFAYETTE COUNTY
LAFAYETTE COUNTY COURT

STRUCTURE C-23

AS BUILT 1-23-70

<i>John W. Lee</i>	8-2-67
<i>Chas. D. Butler</i>	8/4/67

| SHEET | APPENDIX A




Property Line 7

DATA TABLE

Drainage Area, Acres	146.0
Permanent Pool Storage, Acre Feet	147.7
Temporary Storage, Acre Feet	32.0
Surface Area, Permanent Pool, Acres	11.8
Surface Area Temporary Pool, Acres	14.3


Structure C-23 located 1 1/2 miles West and 1/2 mile South of Wellington Mo in SW 1/4 Sec 20 Twp 30N R23W



AS BUILT 1-23-70

STRUCTURE C-23	
WELLINGTON-NAPOLEON WATERSHED PL 566	
LAFAYETTE COUNTY, MISSOURI	
U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE	
Drawn by	Scale
Checked by	1:50
Approved by	
Date	1-23-70

Top of brass cap in concrete monument located in fence corner on emergency spillway and of dam approx. 50' north of west gate. SW 1/4 Sec. 20, T30N, R20W





OMER & ERNE E. BORGMAN

1. The first group of people who are interested in the study of the history of the United States are the people who are interested in the history of the United States.


PLAN OF EMBA

50_





PLAN OF EMBANKMENT AND SPILLWAYS






QUANTITIES	
Excavation Common R.C.	
Core Trench	1222 cu Yd.
Stream Channel	1876 cu Yd.
Total	3208 cu Yd.
Earth Fill	
Class A	44,289 cu Yd.
Fence-Barbed Wire	1876 linear ft.

AS BUILT 1-25-70

STRUCTURE C-23	
WELLINGTON-NAPOLEON WATERSHED PL. 566	
LAFAYETTE COUNTY, MISSOURI	
U. S. DEPARTMENT OF AGRICULTURE	
SOIL CONSERVATION SERVICE	
Drawn by	W. H. H. H.
Checked by	W. H. H. H.
Approved by	W. H. H. H.
Date	1-25-70

SHEET 3 APPENDIX A






Dist	Area
0+00	72.34
0+10	72.34
0+20	72.34
0+30	72.34
0+40	72.34
0+50	72.34
0+60	72.34
0+70	72.34
0+80	72.34
0+90	72.34
1+00	72.34
1+10	72.34
1+20	72.34
1+30	72.34
1+40	72.34
1+50	72.34
1+60	72.34
1+70	72.34
1+80	72.34
1+90	72.34
2+00	72.34

QUANTITIES

- Concrete-Class 2500, Plain
- Concrete-Class 4000, Reinforced
- Steel bar Reinforcement
- Pipe-Conduit-Pressure Concrete (Pressure) 24" Diam. Steel Ring Type Unit
- Excavation-Trench Back
- Fill, Antiseep-Cement (Pressure) 6" Diam. Class IV
- Fill, Antiseep-Cement (Pressure) 6" Diam. Class IV
- Fill, Antiseep-Cement (Pressure) 6" Diam. Class IV
- Fill, Antiseep-Cement (Pressure) 6" Diam. Class IV
- Installing Vertical Drains

2




- N.B.:
1. Camber conduit in accordance with the elevations given in the table below
 2. Conduit elevations other than those shown will be furnished by the Engineer, when reqd.
 3. Antiseep collars shall not be placed closer than two (2) feet to a pipe joint

QUANTITIES

18.0 Cu Yds	
52.2 Cu Yds	
263R 4-60 Hards	
184 Lin Ft	
2000 Cu Yds	
40 Lin Ft	
90	
107 00 Cu Yds	
64 Lin Ft	

AS BUILT 1-29-70
STRUCTURE C-22


W/C DROP INLET FOR 24" DIAM. PIPE			
GENERAL LAYOUT			
WELLINGTON-HIAPOLEON WATERSHED PL556			
LAFAYETTE COUNTY, MISSOURI			
U. S. DEPARTMENT OF AGRICULTURE			
SOIL CONSERVATION SERVICE			
Drawn by	11/7/64	Checked by	
Eng. by	10/64	Approved by	
Scale		Sheet No.	25-25/10
Job No.	100	Drawn by	JIT



PRECEDING PAGE BLANK-NOT FILMED


APPENDIX B

0+00 1+00 2+00 3+00 4+00 5+00



A 100'
B 100'
C 100'
D 100'
E 100'
F 100'
G 100'
H 100'
I 100'

[Faint, illegible text, possibly a legend or notes]



PLAN OF DAM, EMERGENCY SPILLWAY AND BORROW AREA (S)

Sta 5100
Grd 8100

780


770

760



GEOLOGIC CROSS SECTIONS OF BORROW AREA (S)

1.



Sheet 1 of 3

UNITED STATES DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

10-29

DETAILED GEOLOGIC INVESTIGATION OF DAM SITES

GENERAL

State Missouri County Lafayette ; SW 1/4 Sec. 20 T 50N R 25W ; Watershed Wellington-Napoleon
Subwatershed _____ Fund class LP-03-10 Site number G-23 Site group I Structure class b
(FP-2, WP-1, etc.)
Investigated by Niel P. Edwards, Geo. Equipment used Mobile 0-40 Date 6-14-66
(signature and title) (type, size, make, model, etc.)

SITE DATA

Drainage area size .23 sq. mi., 146 acres. Type of structure DI 24"RC Purpose Stabilization, Sediment, Detention
Direction of valley trend (downstream) SW Maximum height of fill 49.5 feet. Length of fill 490 feet.
Estimated volume of compacted fill required 30,000 yards

STORAGE ALLOCATION

	Volume (ac. ft.)	Surface Area (acres)	Depth at Dam (feet)
Sediment	<u>160.0</u>	<u>12.8</u>	<u>45.0</u>
Floodwater	<u>20.5</u>	<u>14.3</u>	<u>46.5</u>

SURFACE GEOLOGY AND PHYSIOGRAPHY

Physiographic description Mo. River Loess Hills Topography Rolling Altitude of beds: Dip _____ Strike _____
Steepness of abutments: Left 15 percent; Right 14 percent. Width of floodplain at centerline of dam 0 feet
General geology of site: The site is located in the loess hills approximately 3/4 mile from the Missouri River floodplain and is in an area underlain with bedrock of the Upper Desmoinesian Series of the Pennsylvanian System which are characterized as cyclic deposits of principally limestone and shale.

DETAILED GEOLOGIC INVESTIGATION OF DAM SITES

NATURE Centerline of Dam, Principal Spillway, Borrow Area

(Centerline of Dam, Principal Spillway, Emergency Spillway, the Stream Channel, Investigations for Drainage of Structure, Borrow Area, Reservoir Basin, etc.)

DRILLING PROGRAM

Equipment Used	Number of Holes		Number of Samples Taken		
	Exploration	Sampling	Undisturbed (state type)	Disturbed Large	Small
FA 4"	2	1		1 L. Bag	
Sp. T		4			
Tube 3"		1	2 Shelby		20 Jar
Total	2	6	2	1	20

SUMMARY OF FINDINGS

(include only factual data)

The abutments are deep loess. The material below the developed soil profile is classified CL except for material classified ML in test hole 3 from 11 to 13 feet. Blow counts in the loess ranged from 2.5 to 16. The foundation of the principal spillway is medium to stiff alluvium classified ML. Sand classified SP was encountered in test hole 3 and 5 and also occurs at a relatively uniform elevation and thickness in test holes 301 and 302. The weakest material of the foundation had a blow count of 2.5 in test hole 5. The emergency spillway cuts will be in the loess soil. The channel is active and cutting. There is sufficient borrow available within 500 feet of the centerline of the dam.

DETAILED GEOLOGIC INVESTIGATION OF DAM SITES

D-59

Wellington-
State Missouri County Lafayette Watershed Napoleon Subwatershed _____
Site number C-23 Site group I Structure class b Investigated by Muel F. Edmonds, Geo. Date 6-14-66
(signature and title)

INTERPRETATIONS AND CONCLUSIONS

The soft loess in test hole 5 is unusual for the loess in this area. There was poor recovery on the sample and some doubt as to the validity of the blow count. Undisturbed samples were taken of the weakest material in the foundation of the principal spillway. The sand in test holes 3 and 5 is interpreted as pockets or lens and as a stratum occurring at relatively uniform elevation and thickness beneath the principal spillway. This material had a blow count of 3 in test holes 301 and 302 and is permeable. The sand is underlain with stiff CH. There is an area of slopewash classified ML on both gully banks.

Emergency spillway cuts are shallow and in loess soil and was not drilled or sampled. The channel is active and has 1 to 2 feet of soft channel fill principally at the sides of the channel. All borrow will be the loess soil. Since this material is uniform in texture and depth, it was felt that one borrow sample was sufficient.

There is an estimated 37,000 cubic yards of compacted fill available below the crest elevation of the principal spillway within 500 feet of the centerline of the dam.

UNITED STATES GOVERNMENT

Memorandum

Design

TO : James M. Dale, State Conservation Engineer,
SCS, Columbia, Missouri 65201

DATE: October 14, 1966

FROM : Roland B. Philips, Acting Head, Soil Mechanics Unit,
SCS, Lincoln, Nebraska 68508

SUBJECT: ENG 22-5, Missouri WP-08, Wellington-Napoleon Site C-23 (Lafayette County)

ATTACHMENTS

1. Form SCS-354, Soil Mechanics Laboratory Data, 4 sheets.
2. Form SCS-128 and 128A, Consolidation Test, 4 sheets.
3. Form SCS-127, Permeability Test, 1 sheet.
4. Form SCS-355A, Triaxial Shear Test, 2 sheets.
5. Form SCS-352, Compaction and Penetration Resistance, 1 sheet.
6. Form SCS-357, Summary - Slope Stability, 3 sheets.

DISCUSSION

FOUNDATION

- A. Classification: The loess and loess derived alluvial materials that blanket the site to depths of 30 feet or more classify generally as low plasticity CL and ML materials with approximately 85% fines.

A sandy layer underlies the floodplain materials at the 30-foot depth. A sample of the deep sandy material, 67W381 (3.4), contained 16% fines, 94% sand and 11% finer than the 2 micron size clay. The deep sandy samples 67W370 (301.5) and 67W377 (302.5) class as SP-SM materials with 9 and 12% fines.

- B. Dry Unit Weight: Core opening dry density of the shallowest core sample 67W371 (301.6) was 1.49 gm/cc; however, the consolidation test specimen had an initial dry density of only 1.22 gm/cc and the shear test specimens of sample 67W371 had an average dry density of only 1.34 gm/cc.

The deeper core sample, 67W372 (301.7), from the 18 to 19.5-foot depths had a core opening dry density of 1.48 gm/cc.

Blow count for the deeper material was 5 blows per foot. The material at the 30-foot depth and below had blow count of 9 blows per foot.

The loess material of the abutments was fairly moist but was above the permanent water table. It had blow count generally in the range of 5 to 8 blows/foot.

2 -- James M. Dale -- 10/14/66

Roland B. Phillips

Subj: ENG 22-5, Missouri WP-08, Wellington-Napolean, Site C-23

- C. Consolidation: A one-dimensional consolidation test was made on the shallow CL alluvial sample 67W371 (301.6). The sample had an initial dry density of only 1.22 gm/cc and contained only 10.3% moisture. The sample was loaded to 4000 psf at natural moisture and then saturated under load to determine the extent of the rapid consolidation that usually occurs when a dry low density silt material is saturated under load. The sample consolidated 11% (from 2 to 13%) when saturated under a 4000 psf load. Approximately 15% total consolidation was obtained from the 5000 psf load which is the equivalent loading of the proposed embankment with a top elevation of 782.5.

The alluvium from 10 to 22 feet in test hole No. 301, which had a blow count of 5 blows per foot, is expected to have a consolidation potential of approximately 4% based on a comparison with the consolidation tests from sites C-21 and C-22.

The 9 and 10 blow count CL materials below 22 feet are estimated to have a consolidation potential of 2% under the proposed 40-foot high embankment.

- D. Permeability: A falling head permeability test was made on the low density consolidation test specimen during the consolidation testing. A semi-log plot of the void ratio versus permeability gives a normal straight line. Extrapolation of the plot to the starting void ratio shows a permeability rate of approximately 2 ft/day for the material at its initial density. The specimen had a permeability rate of 0.05 ft/day under the 4000 psf loading at a density of 1.41 gm/cc.

The permeability of the higher blow count ($n = 9$) CL material is expected to be approximately 0.001 ft/day. Permeability of the deep underlying SP-SM materials is estimated at 10 ft/day. (From Slichter's permeability charts in "Low Dam")

Uplift appears to present a problem in the outlet channel area. Calculations based on a 20-foot blanket under the channel ($K_b = .001$ ft/day) over a 10-foot aquifer ($K_f = 10$ ft/day) show a safety factor less than 1.0 if relief is not provided. A deeply eroded plunge basin could easily reduce the 20-foot blanket thickness and blowout or boils would occur as the permanent water table is near the top of the dam in this grade control structure. A relief well on each side of the principal spillway at $c/b = 0.8$ would effectively relieve the uplift pressure.

3 -- James M. Dale -- 10/14/66

Roland B. Phillips

Subj: ENG 22-5, Missouri WP-08, Wellington-Napolean, Site C-23

- E. Shear Strength: A consolidated, undrained triaxial shear test on the low density CL sample, 67W371 (301.6) gave saturated total stress shear parameters of $\phi = 20.5^\circ$, $c = 425$ psf.

The deeper, more dense foundation materials are expected to be as strong or stronger than the shallow sample, 67W371 (301.6).

EMBANKMENT

- A. Classification: The only borrow sample submitted, 67W387 (102.1), was a moderately plastic CL material with 93% fines and 24% smaller than the 2 micron size.
- B. Compacted Dry Density: Standard Proctor compaction (ASTM D-698) yielded a maximum dry density of 103.5 pcf with an optimum moisture content of 19.0%.
- C. Shear Strength: A consolidated, undrained triaxial shear test on remolded specimens of Sample 67W387 (102.1) at dry densities of approximately 93% of standard (98.6 pcf) gave saturated total stress shear parameters of $\phi = 10^\circ$ and $c = 1150$ psf.
- D. Consolidation: An average consolidation potential of 2% is estimated for the 40-foot high embankment across the floodplain.

STABILITY ANALYSIS

A modified Swedish circle method of analysis was used to analyze the embankment stability. Shear parameters of $\phi = 10^\circ$ and $c = 1150$ psf were used to represent the shear strength of the embankment and parameters of $\phi = 20.5^\circ$ and $c = 425$ psf were used to represent the foundation. The foundation parameters of $\phi = 20.5^\circ$ and $c = 425$ psf from the shallow sample, 67W371, are rather low for the full 22 feet of foundation cut by the arcs in the floodplain section; however, satisfactory safety factors were obtained for the proposed design using the low values so further refinement is not necessary.

A safety factor of 1.41 was obtained for the 2 1/2:1 upstream slope of the maximum section with a 10-foot berm at elevation 778.0 (see trial No. 1 in the slope stability summary in the attachments). The downstream 2 1/2:1 slope without a drain but with a berm at elevation 760 gave a safety factor of 1.71 for the 49.5-foot high maximum section of the proposed Class "B" structure.

4 -- James M. Dale -- 10/14/66

Roland B. Phillips

Subj: ENG 22-5, Missouri WP-08, Wellington-Napolean, Site C-23

RECOMMENDATIONS

- A. Site Preparation: Removal of 8 feet of the low density surface alluvium in the gully on each side of the present channel is recommended to reduce the horizontal strain on the conduit.
- B. Centerline Cutoff: A normal width ^{12'}(10') cutoff approximately 5 feet deep is recommended to penetrate the zone of surface weathering and slope wash materials. Side slopes of 1:1 are adequate for the cutoff trench. Backfill with CL borrow material compacted to 95% of standard.
- C. Principal Spillway: Pipe elongation calculations for $\frac{1}{2}$ station 3+50 based on 25 feet of compressible foundation (with 8 feet of the low density surface material removed) with an average consolidation potential of 4.0% show a horizontal strain of approximately 0.01 ft/ft for a 45-foot high embankment.
- A ϕ angle of 25° is recommended for conduit loading calculations.
- Backfill with CL material compacted to a minimum density of 95% of standard.
- D. Drainage: Relief wells at $c/b = 0.8$ on each side of the principal spillway are recommended to penetrate the sand layer at elevation 712 to relieve uplift pressures in the plunge basin to avoid blow-out or "boils".
- E. Embankment Design: The following are recommended:
1. Place the CL borrow materials in a homogeneous embankment at a minimum density of 95% of standard. Place materials at a moisture content on the wet side of optimum.
 2. Provide 2 1/2:1 embankment slopes both upstream and downstream.
 3. Provide a 10-foot upstream berm at elevation 778.0, and a 15-foot downstream berm at elevation 760.0.
 4. Provide an overfill of 2.0 feet across the floodplain of the gully from station 3+00 to station 4+50 to compensate for residual foundation and embankment settlement.

Prepared by:

Edgar F. Steele
Edgar F. Steele

Attachments

cc:


James M. Dale (2)
Project Engineer

E. S. Alling
D. S. McVicker

SHEET 9 APPENDIX B ?

4. 0.28
 106 0.220
 70
 0.16
 A points plotted from computer
 Output data

Elev	Area	Storage
777.0	11.8	1477
777.23		158.5
777.46		158.8
777.70		156.2
778.0	12.8	
778.42		165.5
778.78		176.4
779.14		175.4
779.51	14.3	180.5
780.01	14.8	187.8
780.51		195.3
781.01		203.0
781.51		210.9
782.01	16.4	218.0



Inflow Hydrograph Coordinates				Outflow Hydrograph Coordinates			
Time	Flow	Time	Flow	Time	Flow	Time	Flow
0	0	0	0	0	0	0	0
0.25	11	0.25	11	0.25	11	0.25	11
0.5	27	0.5	27	0.5	27	0.5	27
0.75	49	0.75	49	0.75	49	0.75	49
1.0	76	1.0	76	1.0	76	1.0	76
1.25	121	1.25	121	1.25	121	1.25	121
1.5	324	1.5	324	1.5	324	1.5	324
1.75	527	1.75	527	1.75	527	1.75	527
2.0	658	2.0	658	2.0	658	2.0	658
2.25	613	2.25	613	2.25	613	2.25	613
2.5	637	2.5	637	2.5	637	2.5	637
2.75	580	2.75	580	2.75	580	2.75	580
3.0	355	3.0	355	3.0	355	3.0	355
3.25	324	3.25	324	3.25	324	3.25	324

CONDUIT

WEIR

CONDUIT

TOTAL

Emergency Spillway (Case 1) **772.5**
 Max. Discharge **79**
 Design Discharge **79**

Structure **C-23**
 Wellington-Napoleon Watershed PL-566
 Lafayette County, Missouri

WEIR **772.0**
 Max. Discharge **79**
 Design Discharge **79**

Design Discharge **79**
 Max. Discharge **79**

Structure **C-23**
 Wellington-Napoleon Watershed PL-566
 Lafayette County, Missouri

WEIR **772.0**
 Max. Discharge **79**
 Design Discharge **79**

Design Discharge **79**
 Max. Discharge **79**

Structure **C-23**
 Wellington-Napoleon Watershed PL-566
 Lafayette County, Missouri

WEIR **772.0**
 Max. Discharge **79**
 Design Discharge **79**

Design Discharge **79**
 Max. Discharge **79**

Structure **C-23**
 Wellington-Napoleon Watershed PL-566
 Lafayette County, Missouri

WEIR **772.0**
 Max. Discharge **79**
 Design Discharge **79**

Design Discharge **79**
 Max. Discharge **79**

Structure **C-23**
 Wellington-Napoleon Watershed PL-566
 Lafayette County, Missouri

WEIR **772.0**
 Max. Discharge **79**
 Design Discharge **79**

Design Discharge **79**
 Max. Discharge **79**

Structure **C-23**
 Wellington-Napoleon Watershed PL-566
 Lafayette County, Missouri

WEIR **772.0**
 Max. Discharge **79**
 Design Discharge **79**

Design Discharge **79**
 Max. Discharge **79**

Structure **C-23**
 Wellington-Napoleon Watershed PL-566
 Lafayette County, Missouri

WEIR **772.0**
 Max. Discharge **79**
 Design Discharge **79**

Design Discharge **79**
 Max. Discharge **79**

Structure **C-23**
 Wellington-Napoleon Watershed PL-566
 Lafayette County, Missouri

WEIR **772.0**
 Max. Discharge **79**
 Design Discharge **79**

Design Discharge **79**
 Max. Discharge **79**

Structure **C-23**
 Wellington-Napoleon Watershed PL-566
 Lafayette County, Missouri

WEIR **772.0**
 Max. Discharge **79**
 Design Discharge **79**

Design Discharge **79**
 Max. Discharge **79**

Structure **C-23**
 Wellington-Napoleon Watershed PL-566
 Lafayette County, Missouri

WEIR **772.0**
 Max. Discharge **79**
 Design Discharge **79**

Design Discharge **79**
 Max. Discharge **79**

Structure **C-23**
 Wellington-Napoleon Watershed PL-566
 Lafayette County, Missouri

WEIR **772.0**
 Max. Discharge **79**
 Design Discharge **79**

Design Discharge **79**
 Max. Discharge **79**

Structure **C-23**
 Wellington-Napoleon Watershed PL-566
 Lafayette County, Missouri

WEIR **772.0**
 Max. Discharge **79**
 Design Discharge **79**

Design Discharge **79**
 Max. Discharge **79**

Structure **C-23**
 Wellington-Napoleon Watershed PL-566
 Lafayette County, Missouri

WEIR **772.0**
 Max. Discharge **79**
 Design Discharge **79**

Design Discharge **79**
 Max. Discharge **79**

Structure **C-23**
 Wellington-Napoleon Watershed PL-566
 Lafayette County, Missouri

WEIR **772.0**
 Max. Discharge **79**
 Design Discharge **79**

Design Discharge **79**
 Max. Discharge **79**

Structure **C-23**
 Wellington-Napoleon Watershed PL-566
 Lafayette County, Missouri

WEIR **772.0**
 Max. Discharge **79**
 Design Discharge **79**

Design Discharge **79**
 Max. Discharge **79**

Structure **C-23**
 Wellington-Napoleon Watershed PL-566
 Lafayette County, Missouri

WEIR **772.0**
 Max. Discharge **79**
 Design Discharge **79**

Design Discharge **79**
 Max. Discharge **79**

Structure **C-23**
 Wellington-Napoleon Watershed PL-566
 Lafayette County, Missouri

WEIR **772.0**
 Max. Discharge **79**
 Design Discharge **79**


Design Discharge **79**
 Max. Discharge **79**

Structure **C-23**
 Wellington-Napoleon Watershed PL-566
 Lafayette County, Missouri

WEIR **772.0**
 Max. Discharge **79**
 Design Discharge **79**

Design Discharge **79**
 Max. Discharge **79**

Structure **C-23**
 Wellington-Napoleon Watershed PL-566
 Lafayette County, Missouri



AS BUILT

STRUCTURE C-23

FLOOD ROUTING

EMERGENCY SPILLWAY HYDROGRAPH
 WELLINGTON-NAPOLEON WATERSHED PL-566
 LAFAYETTE COUNTY, MISSOURI

U. S. DEPARTMENT OF AGRICULTURE
 SOIL CONSERVATION SERVICE

Prepared by **B. E. Smith** Date **6/96**
 Checked by **B. E. Smith** Date **6/96**
 Drawn by **B. E. Smith** Date **6/96**


Time in Hours	Inflow cfs	Outflow cfs	Storage Used cfs-hr
0	0	0	0
1	191	258	167
2	203	268	165
3	213	274	161
4	221	276	155
5	226	276	147
6	229	274	137
7	230	270	125
8	229	264	111
9	226	256	90
10	221	246	75
11	213	234	59
12	203	220	43
13	191	204	27
14	177	186	11
15	161	166	-5
16	143	143	-20
17	123	123	-35
18	101	101	-50
19	77	77	-65
20	51	51	-80
21	26	26	-95
22	0	0	-110

SUMMARY DATA	
Top of Embankment	772.50
Emergency Spillway	772.50
High Stage	772.50
Low Stage	772.50
Design Discharge	79
Max. Discharge	79
Time to Peak	10
Time to Base	20
Storage Used	167
Design Discharge	79
Max. Discharge	79
Time to Peak	10
Time to Base	20
Storage Used	167

PRECEDING PAGE BLANK-NOT FILLED

See Note Sheet 1 of 3

For Watershed, Storage and Discharge



10.11	14.21	0.16	50	50	1.50	1221
7.1	14.21	0.16	50	50	1.66	1027
10.11	14.21	0.16	50	50	1.78	764
10.11	14.21	0.16	50	50	1.82	663
10.11	14.21	0.16	50	50	1.97	550
10.11	14.21	0.16	50	50	2.08	460
10.11	14.21	0.16	50	50	2.34	365
10.11	14.21	0.16	50	50	2.61	284
10.11	14.21	0.16	50	50	2.87	246
10.11	14.21	0.16	50	50	2.98	240
10.11	14.21	0.16	50	50	3.13	225
10.11	14.21	0.16	50	50	3.39	203
10.11	14.21	0.16	50	50	3.65	185
10.11	14.21	0.16	50	50	3.81	171

.....

2

... ..
... ..
... ..
... ..

[illegible]

1990

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

1 07 000000 000000 00 00
2 00 00 00 00 00 00
3 00 00 00 00 00 00
4 00 00 00 00 00 00
5 00 00 00 00 00 00
6 00 00 00 00 00 00
7 00 00 00 00 00 00
8 00 00 00 00 00 00
9 00 00 00 00 00 00
10 00 00 00 00 00 00
11 00 00 00 00 00 00
12 00 00 00 00 00 00
13 00 00 00 00 00 00
14 00 00 00 00 00 00
15 00 00 00 00 00 00
16 00 00 00 00 00 00
17 00 00 00 00 00 00
18 00 00 00 00 00 00
19 00 00 00 00 00 00
20 00 00 00 00 00 00
21 00 00 00 00 00 00
22 00 00 00 00 00 00
23 00 00 00 00 00 00
24 00 00 00 00 00 00
25 00 00 00 00 00 00
26 00 00 00 00 00 00
27 00 00 00 00 00 00
28 00 00 00 00 00 00
29 00 00 00 00 00 00
30 00 00 00 00 00 00
31 00 00 00 00 00 00
32 00 00 00 00 00 00
33 00 00 00 00 00 00
34 00 00 00 00 00 00
35 00 00 00 00 00 00
36 00 00 00 00 00 00
37 00 00 00 00 00 00
38 00 00 00 00 00 00
39 00 00 00 00 00 00
40 00 00 00 00 00 00
41 00 00 00 00 00 00
42 00 00 00 00 00 00
43 00 00 00 00 00 00
44 00 00 00 00 00 00
45 00 00 00 00 00 00
46 00 00 00 00 00 00
47 00 00 00 00 00 00
48 00 00 00 00 00 00
49 00 00 00 00 00 00
50 00 00 00 00 00 00
51 00 00 00 00 00 00
52 00 00 00 00 00 00
53 00 00 00 00 00 00
54 00 00 00 00 00 00
55 00 00 00 00 00 00
56 00 00 00 00 00 00
57 00 00 00 00 00 00
58 00 00 00 00 00 00
59 00 00 00 00 00 00
60 00 00 00 00 00 00
61 00 00 00 00 00 00
62 00 00 00 00 00 00
63 00 00 00 00 00 00
64 00 00 00 00 00 00
65 00 00 00 00 00 00
66 00 00 00 00 00 00
67 00 00 00 00 00 00
68 00 00 00 00 00 00
69 00 00 00 00 00 00
70 00 00 00 00 00 00
71 00 00 00 00 00 00
72 00 00 00 00 00 00
73 00 00 00 00 00 00
74 00 00 00 00 00 00
75 00 00 00 00 00 00
76 00 00 00 00 00 00
77 00 00 00 00 00 00
78 00 00 00 00 00 00
79 00 00 00 00 00 00
80 00 00 00 00 00 00
81 00 00 00 00 00 00
82 00 00 00 00 00 00
83 00 00 00 00 00 00
84 00 00 00 00 00 00
85 00 00 00 00 00 00
86 00 00 00 00 00 00
87 00 00 00 00 00 00
88 00 00 00 00 00 00
89 00 00 00 00 00 00
90 00 00 00 00 00 00
91 00 00 00 00 00 00
92 00 00 00 00 00 00
93 00 00 00 00 00 00
94 00 00 00 00 00 00
95 00 00 00 00 00 00
96 00 00 00 00 00 00
97 00 00 00 00 00 00
98 00 00 00 00 00 00
99 00 00 00 00 00 00
100 00 00 00 00 00 00

... ..

.....

1. *Chlorophyll a* and *Chlorophyll b* were determined by the method of Arar and Collins (1971) using a Shimadzu 1601 UV-Visible Spectrophotometer. The concentration of chlorophyll was expressed in mg/L.

[illegible]

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

BILT

GOOD ROUTING

BOARD HYDROGRAPH
OLEON WATERSHED PL-566
COUNTY, MISSOURI
ENT OF AGRICULTURE


RESERVATION SERVICE	
Date	Reservado By
11/22	
11/22	

APPENDIX B

10. *Chlorophyll a* and *Chlorophyll b* were determined by the method of Arar and Collins (1971).

100

Ag. 51.



AS BUILT

STRUCTURE C-23

FLOOD ROUTING

FREEBOARD

HYDROGRAPH

WELLINGTON-NAPOLEON WATERSHED PL-566
LAFAYETTE COUNTY, MISSOURI

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

Page 2 of 2

_____ Randolph G. Hooper 967-2 86-26170-4

HEET II APPENDIX

100

1.58	12.21	4.17	160
1.66	10.27	4.43	160
1.78	7.64	4.69	150
1.82	6.65	4.95	150
1.97	3.50	5.23	139
2.08	4.63	5.48	11
2.34	3.63	5.64	4
2.61	2.54	5.79	0
2.87	2.46		
2.98	2.40		
3.13	3.25		
3.39	2.09		
3.65	1.62		
3.91	1.71		

[illegible]

SHEET 11 APPENDIX B

STAGE	
1ST	
2ND	
3RD	
4TH	
5TH	
6TH	
7TH	
8TH	
9TH	
10TH	
11TH	
12TH	
13TH	
14TH	
15TH	
16TH	
17TH	
18TH	
19TH	
20TH	
21ST	
22ND	
23RD	
24TH	
25TH	
26TH	
27TH	
28TH	
29TH	
30TH	
31ST	
32ND	
33RD	
34TH	
35TH	
36TH	
37TH	
38TH	
39TH	
40TH	
41ST	
42ND	
43RD	
44TH	
45TH	
46TH	
47TH	
48TH	
49TH	
50TH	
51ST	
52ND	
53RD	
54TH	
55TH	
56TH	
57TH	
58TH	
59TH	
60TH	
61ST	
62ND	
63RD	
64TH	
65TH	
66TH	
67TH	
68TH	
69TH	
70TH	
71ST	
72ND	
73RD	
74TH	
75TH	
76TH	
77TH	
78TH	
79TH	
80TH	
81ST	
82ND	
83RD	
84TH	
85TH	
86TH	
87TH	
88TH	
89TH	
90TH	
91ST	
92ND	
93RD	
94TH	
95TH	
96TH	
97TH	
98TH	
99TH	
100TH	

STATION	TIME	DATE	REMARKS
100	23	2-20	
101	23	2-20	
102	23	2-20	
103	23	2-20	
104	23	2-20	
105	23	2-20	
106	23	2-20	
107	23	2-20	
108	23	2-20	
109	23	2-20	
110	23	2-20	
111	23	2-20	
112	23	2-20	
113	23	2-20	
114	23	2-20	
115	23	2-20	
116	23	2-20	
117	23	2-20	
118	23	2-20	
119	23	2-20	
120	23	2-20	
121	23	2-20	
122	23	2-20	
123	23	2-20	
124	23	2-20	
125	23	2-20	
126	23	2-20	
127	23	2-20	
128	23	2-20	
129	23	2-20	
130	23	2-20	
131	23	2-20	
132	23	2-20	
133	23	2-20	
134	23	2-20	
135	23	2-20	
136	23	2-20	
137	23	2-20	
138	23	2-20	
139	23	2-20	
140	23	2-20	
141	23	2-20	
142	23	2-20	
143	23	2-20	
144	23	2-20	
145	23	2-20	
146	23	2-20	
147	23	2-20	
148	23	2-20	
149	23	2-20	
150	23	2-20	
151	23	2-20	
152	23	2-20	
153	23	2-20	
154	23	2-20	
155	23	2-20	
156	23	2-20	
157	23	2-20	
158	23	2-20	
159	23	2-20	
160	23	2-20	
161	23	2-20	
162	23	2-20	
163	23	2-20	
164	23	2-20	
165	23	2-20	
166	23	2-20	
167	23	2-20	
168	23	2-20	
169	23	2-20	
170	23	2-20	
171	23	2-20	
172	23	2-20	
173	23	2-20	
174	23	2-20	
175	23	2-20	
176	23	2-20	
177	23	2-20	
178	23	2-20	
179	23	2-20	
180	23	2-20	
181	23	2-20	
182	23	2-20	
183	23	2-20	
184	23	2-20	
185	23	2-20	
186	23	2-20	
187	23	2-20	
188	23	2-20	
189	23	2-20	
190	23	2-20	
191	23	2-20	
192	23	2-20	
193	23	2-20	
194	23	2-20	
195	23	2-20	
196	23	2-20	
197	23	2-20	
198	23	2-20	
199	23	2-20	
200	23	2-20	

—

10/10/54	0800	1000	10	15	1	1000
10/10/54	0900	1000	10	15	1	1000
10/10/54	1000	1000	10	15	1	1000
10/10/54	1100	1000	10	15	1	1000
10/10/54	1200	1000	10	15	1	1000
10/10/54	1300	1000	10	15	1	1000
10/10/54	1400	1000	10	15	1	1000
10/10/54	1500	1000	10	15	1	1000
10/10/54	1600	1000	10	15	1	1000
10/10/54	1700	1000	10	15	1	1000
10/10/54	1800	1000	10	15	1	1000
10/10/54	1900	1000	10	15	1	1000
10/10/54	2000	1000	10	15	1	1000
10/10/54	2100	1000	10	15	1	1000
10/10/54	2200	1000	10	15	1	1000
10/10/54	2300	1000	10	15	1	1000
10/10/54	0000	1000	10	15	1	1000
10/10/54	0100	1000	10	15	1	1000
10/10/54	0200	1000	10	15	1	1000
10/10/54	0300	1000	10	15	1	1000
10/10/54	0400	1000	10	15	1	1000
10/10/54	0500	1000	10	15	1	1000
10/10/54	0600	1000	10	15	1	1000
10/10/54	0700	1000	10	15	1	1000
10/10/54	0800	1000	10	15	1	1000
10/10/54	0900	1000	10	15	1	1000
10/10/54	1000	1000	10	15	1	1000
10/10/54	1100	1000	10	15	1	1000
10/10/54	1200	1000	10	15	1	1000
10/10/54	1300	1000	10	15	1	1000
10/10/54	1400	1000	10	15	1	1000

10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259 260 261 262 263 264 265 266 267 268 269 270 271 272 273 274 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307 308 309 310 311 312 313 314 315 316 317 318 319 320 321 322 323 324 325 326 327 328 329 330 331 332 333 334 335 336 337 338 339 340 341 342 343 344 345 346 347 348 349 350 351 352 353 354 355 356 357 358 359 360 361 362 363 364 365 366 367 368 369 370 371 372 373 374 375 376 377 378 379 380 381 382 383 384 385 386 387 388 389 390 391 392 393 394 395 396 397 398 399 400 401 402 403 404 405 406 407 408 409 410 411 412 413 414 415 416 417 418 419 420 421 422 423 424 425 426 427 428 429 430 431 432 433 434 435 436 437 438 439 440 441 442 443 444 445 446 447 448 449 450 451 452 453 454 455 456 457 458 459 460 461 462 463 464 465 466 467 468 469 470 471 472 473 474 475 476 477 478 479 480 481 482 483 484 485 486 487 488 489 490 491 492 493 494 495 496 497 498 499 500 501 502 503 504 505 506 507 508 509 510 511 512 513 514 515 516 517 518 519 520 521 522 523 524 525 526 527 528 529 530 531 532 533 534 535 536 537 538 539 540 541 542 543 544 545 546 547 548 549 550 551 552 553 554 555 556 557 558 559 560 561 562 563 564 565 566 567 568 569 570 571 572 573 574 575 576 577 578 579 580 581 582 583 584 585 586 587 588 589 590 591 592 593 594 595 596 597 598 599 600 601 602 603 604 605 606 607 608 609 610 611 612 613 614 615 616 617 618 619 620 621 622 623 624 625 626 627 628 629 630 631 632 633 634 635 636 637 638 639 640 641 642 643 644 645 646 647 648 649 650 651 652 653 654 655 656 657 658 659 660 661 662 663 664 665 666 667 668 669 670 671 672 673 674 675 676 677 678 679 680 681 682 683 684 685 686 687 688 689 690 691 692 693 694 695 696 697 698 699 700 701 702 703 704 705 706 707 708 709 710 711 712 713 714 715 716 717 718 719 720 721 722 723 724 725 726 727 728 729 730 731 732 733 734 735 736 737 738 739 740 741 742 743 744 745 746 747 748 749 750 751 752 753 754 755 756 757 758 759 760 761 762 763 764 765 766 767 768 769 770 771 772 773 774 775 776 777 778 779 780 781 782 783 784 785 786 787 788 789 790 791 792 793 794 795 796 797 798 799 800 801 802 803 804 805 806 807 808 809 810 811 812 813 814 815 816 817 818 819 820 821 822 823 824 825 826 827 828 829 830 831 832 833 834 835 836 837 838 839 840 841 842 843 844 845 846 847 848 849 850 851 852 853 854 855 856 857 858 859 860 861 862 863 864 865 866 867 868 869 870 871 872 873 874 875 876 877 878 879 880 881 882 883 884 885 886 887 888 889 890 891 892 893 894 895 896 897 898 899 900 901 902 903 904 905 906 907 908 909 910 911 912 913 914 915 916 917 918 919 920 921 922 923 924 925 926 927 928 929 930 931 932 933 934 935 936 937 938 939 940 941 942 943 944 945 946 947 948 949 950 951 952 953 954 955 956 957 958 959 960 961 962 963 964 965 966 967 968 969 970 971 972 973 974 975 976 977 978 979 980 981 982 983 984 985 986 987 988 989 990 991 992 993 994 995 996 997 998 999 1000 1001 1002 1003 1004 1005 1006 1007 1008 1009 1010 1011 1012 1013 1014 1015 1016 1017 1018 1019 1020 1021 1022 1023 1024 1025 1026 1027 1028 1029 1030 1031 1032 1033 1034 1035 1036 1037 1038 1039 1040 1041 1042 1043 1044

[illegible]

STRUCTURE DATA

STRUCTURE	SITE NUMBER			C-23
	TIME OF CONCENTRATION	HOURS		0.16
	RUNOFF CURVE NUMBER			70
INFLOW	MOISTURE CONDITION			17
	STORM DISTRIBUTION CURVE			2
HYDROGRAPH	HYDROGRAPH FAMILY	PRIN		3.6
	FREEBOARD	PRIN		30
	USED	PRIN		30
DESIGN	STORM DURATION	PRIN	HOURS	6
	POINT RAINFALL	PRIN	INCHES	3.18
	FREEBOARD	PRIN	INCHES	8.25
	RUNOFF Q	PRIN	INCHES	10.21
	FREEBOARD	PRIN	INCHES	2.17
	STORM FREQ	PRIN	YEARS	50
	SPILLWAY			
EMERGENCY	H ₀ MAX	FEET		0.1
	Q ₀ MAX	CFS/FT		0.5
SPILLWAY	V ₀ MAX	FT/SEC		1.7
	Q ₀ MIN	FT/FT		0.04
DATA	PERMISSIBLE V ₀ MAX	FT/SEC		9.1
	Q ₀ MAX	FT/FT		
	V ₀ MAX	FT/SEC		1.7
	DRAWDOWN TIME	HOURS		62
STRUCTURE	HEIGHT & STORAGE			8393
	CLASS			6


CHANNEL HYDRAULICS

AS BUILT

GENERAL DESIGN DATA	
STRUCTURE C-23	
WELLINGTON-WAVERLY WATERSHED P. 566	
CLAYETTE COUNTY, MISSOURI	
U.S. DEPARTMENT OF AGRICULTURE	
SOIL CONSERVATION SERVICE	
Designed by	Checked by
Reviewed by	Approved by
Date	Date
6/66	6/66
6/66	6/66
6/66	6/66
6/66	6/66

SHEET 12 APPENDIX B

APPENDIX C



Sheet 1 of 3
Appendix C

HYDRAULIC AND HYDROLOGIC DATA

DESIGN DATA: From As Built Plans and Field Measurements

EXPERIENCE DATA: No records are available. The owner stated that to his knowledge the lake has never filled. The apparent high water mark is at elevation 766, which is 10.3 ft below the primary spillway crest of 776.3 ft.

VISUAL INSPECTION: At the time of inspection, the pool elevation was 761.7, which is about 14.6 ft below the primary spillway crest.

OVERTOPPING POTENTIAL: Flood routings were performed to determine the overtopping potential. Since the dam is of intermediate size with a high hazard rating, a Spillway Design Storm of 100 percent of the PMF was prescribed by the guidelines. The Probable Maximum Flood (PMF) is defined as the flood discharge that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region. Reservoir area and storage data and the watershed drainage data were obtained from the As-Built plans. A 5 minute interval unit graph was developed for this watershed area which resulted in a peak inflow of 745 c.f.s. and a time to peak of 10 minutes. Application of the probable maximum precipitation minus losses resulted in a flood hydrograph peak inflow of 3202 c.f.s. (see Sheet 5 of 7). Rainfall distribution for the 24 hour storm was according to EM 1110-2-1411. Considering all factors, the combination of dam, spillway and storage is not sufficient to pass the PMF without overtopping. The embankment crest (El. 782.8) would be overtopped by 1.17 ft at flood pool elevation 783.97.

Fifty percent of the PMF was routed through the spillways. The resultant maximum pool elevation was 782.68, 0.12 ft below the low elevation of the dam (782.8 ft). The peak outflow was 319 c.f.s. The portion of the PMF that will just reach the top of the dam at elevation 782.8 ft is about 0.54. The existing spillway system will be able to pass the 100 year frequency flood without overtopping. For additional data see Summary of Dam Safety Analysis Sheets 3 and 4 of this Appendix.

OVERTOPPING ANALYSIS FOR Dam C-23

INPUT PARAMETERS

1. Unit Hydrograph - SCS Dimensionless - Flood Hydrograph Package (HLC-1); Dam Safety Version Was Used.
Hydraulic Inputs Are As Follows:

- a. Twenty-four Hour Rainfall of 25 Inches
For 200 Square Miles - All Season Envelope
- b. Drainage Area = 146 Acres; = .23 Sq. Miles
- c. Travel Time of Runoff .16 Hrs.; Lag Time 0.1 Hrs.
- d. Soil Conservation Service Runoff Curve No. 85
(AMC III)
- e. Proportion of Drainage Basin Impervious 0.08

2. Spillways

- a. Primary Spillway: Drop Inlet Concrete Structure
(Crest El. 776.3) with 24 in. diameter RCP Pipe
- b. Emergency Spillway: Trapezoidal Cut-seeded
(Crest El. 779.6)
Length 20 Ft.; Side Slopes 3:1; C = 2.65
- c. Dam Overflow


Length 500 Ft.; Side Slopes vertical; C = 3.0

Note: Combined Spillway and Dam Rating Curve Computed
by Hanson Engineers. Data Provided To Computer on
Y4 and Y5 Cards.

SUMMARY OF DAM SAFETY ANALYSIS

- L. Unit Hydrograph
 - a. Peak - 745 c.f.s.
 - b. Time to Peak 10 Min.

2. Flood Routings Were Computed by the Modified Puls Method
 - a. Peak Inflow (see Sheet 5)
50% PMF 1601 c.f.s.; 100% PMF 3202 c.f.s.
 - b. Maximum Reservoir Elevation
50% PMF 782.68; 100% PMF 783.97 c.f.s.
 - c. Portion of PMF That Will Reach Top of Dam
54%; Top of Dam Elev. 782.8 Ft.
3. Computer Input and Output Data Sheets 6 and 7



LAFAYETTE CO DAM C-23 PROBABLE MAXIMUM FLOOD (INPUT DATA)

A ***** OVERTOPPING ANALYSIS FOR LAFAYETTE CO DAM C-23 (HEC-1) DAM SAFETY
 A ***** CO CODE: 107 CO. NAME LAFAYETTE STATE ID NO 10263 DWR. OWNER AND D
 A ***** HANSON ENGINEERS INC. DAM SAFETY INSPECTION (JOB NO 03778) *****

B 300 0 5 0 0 0 0 0 4
 B1 5

J 1 8 1
 J1 0.2 0.30 0.40 0.50 0.60 0.70 0.80 1.00
 K 0 1 3 1

K1 ***** INFLOW HYDROGRAPH COMPUTATION *****

M 1 2 0.23 0.23 1.00 1
 P 25.0 102 120 130

T -1 -95

W2 0.16 10
 X 0.0 -10 2.0
 K 1 0.23 0 1

K1 ***** RESERVOIR ROUTING BY MODIFIED POLS *****

Y 1 1
 1 1
 Y4 776 3 778 779 780 781 782 783 784 785
 Y5 0 74 75 98 100 327 500 2580 5821
 75 0 103 160 174 188 203 219 235 252
 7E 778 778 779 780 781 782 783 784
 75 776 3
 7D 782 8
 K 99

0001

2

(INPUT DATA)

LPN C-23 (HEC-1) DAN SAFETY PROGRAM
E ID NO 10263 QWR. ONER AND DERNA BORGHAN*****
SECTION (JOB NO 03778) *****
0 0 0 4 0

70 0.80 -1.00
3 1

00 1
-1 -85 .08

2 784 785
327 2500 5821
203 219 235 252 268
781 782 783 784 785

Sheet 6 Appendix C

***** PAGE 0001

LAFAYETTE CO DAM 1-23 ARTIFICIAL MAXIMUM FLOOD (OUTPUT DATA)

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-
FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS)
AREA IN SQUARE MILES (SQUARE KILOMETER)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO			
				RATIO 1	RATIO 2	RATIO 3	RATIO 4
				0.20	0.30	0.40	0.50
HYDROGRAPH AT	1	0.23	1	640.	961.	1281.	1601.
	(0.60)	(18.13)	27.20)	36.27)	45.31)
ROUTED TO	23	0.23	1	81.	148.	239.	319.
	(0.60)	(2.30)	4.18)	6.76)	9.00)

1

SUMMARY OF DAM SAFETY ANAL

PLAN	ELEVATION	INITIAL VALUE	SPILLWAY CRES
	777.00		776.30
STORAGE	145.		145
OUTFLOW	30		0

RATIO	PLAN	INITIAL VALUE	SPILLWAY CRES
0.20	779.20	0.00	178.
0.30	780.00	0.00	196.
0.40	781.50	0.00	212.
0.50	782.00	0.00	230.
0.60	783.10	0.39	238.
0.70	783.40	0.66	243.
0.80	783.72	0.92	247.
1.00	783.97	1.17	252.

ROUTED DATA

100% SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 C FEET PER SECOND (CUBIC METERS PER SECOND)
 IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS


1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7	RATIO 8
20	0.30	0.40	0.50	0.60	0.70	0.80	1.00
40	961	1281	1601	1921	2241	2562	3202
13X	27.20X	36.27X	45.34X	54.40X	63.47X	72.54X	90.67X
81	148	239	319	373	1453	1990	2522
30X	4.18X	6.76X	9.02X	24.73X	41.14X	56.36X	71.41X

SUMMARY OF DAM SAFETY ANALYSIS

INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
777.00	776.30	782.80
145.	145	232.
30	0	327.

PLAN	MINIMUM DEPTH	MAXIMUM OUTFLOW	DURATION OVER TOP	TIME OF MAX OUTFLOW	TIME OF FAILURE
FEET DAM	FEET	CFS	HOURS	HOURS	HOURS
0.00	178.	81	0.00	18.00	0.00
0.27	196.	148.	0.00	17.08	0.00
0.00	212.	239.	0.00	16.17	0.00
0.00	230.	319	0.00	16.17	0.00
0.38	238.	873.	1.08	15.83	0.00
0.66	243.	1453	1.75	15.75	0.00
0.92	247.	1990.	2.50	15.75	0.00
1.17	252.	2522.	3.17	15.67	0.00

APPENDIX D



Top of Dam Along Axis - From North Abutment



Primary Spillway Outlet - Looking Downstream



Primary Spillway Outlet - Looking Upstream Toward North Abutment

Sheet 2 of 5
Appendix D



Primary Spillway Outlet - Looking Toward North Abutment

Sheet 3 of 5

Appendix D



Primary Spillway Outlet - Looking Toward South Abutment

Sheet 4 of 5

Appendix D



Lake and Watershed - Looking Upstream